## DEPARTMENT OF TRANSPORTATION

FEDERAL RAILROAD ADMINISTRATION (FRA)

FORM FRA F 6180.96 (Revised 07/14) \*SNFR-Special Notice for Repairs

## **INSPECTION REPORT**

Inchec	tor's Name	In	Inspector's Signature Inspe							ector's ID No	Damas	4 No		Date							
Inspector's Name						Inspector's Signature							Illisp	ector's ID No.	Repor	it No.	уу	mm	dd		
	ell, Raymon							Н	[4103	15	3	2018	11	20							
1 7									R/C		Divis	ion		RR/Co. Representative (Receipt Acknowledged)							
Zenith Energy Terminals										C	SYS	TEM		Name NATHAN EGGERS							
5501 NW FRONT AVE										Co.	Subdi	ivision		Title TERMINAL MANAGER							
DOD'	TI AND	0′					TH	SYS	TEM		Email	nathan.eggers@zenithterminals.com									
POR	TLAND			OR	. 9	97210								Signature							
														Signature	<u> </u>						
From: City PORTLAND Codes 1						Destination City & Co				ity				Codes	From Latitude						
State	OR				41	.1 City									From Longitude						
County MULTNOMAH						CO51 County									To Latitude						
Mile F	Post: From			То		Inspe	ection Po	int BN	SF WII	LLBR	IDGE	YARE	)	1	To Longitude						
Activit Code:	Activity NFY			TCT	172C																
Units:				1	1	1															
Sub Units: 0		0		0	1																
Item	em Initials/Milepost Equipment/Track #		Type/Kind	Defect Subrule			Speed (			Class	Train #/Site	SNFI		* RCL**	# of	Activity					
						USC						•				N		Occ.***	Code		
	1											_					N	0			
	ption - [** C																				
I condi Termii	ucted an insp nal.	ection	at the	BNSF willb	ridge yard f	or com	pliance	with the	e HMR	of 49	CFR.	Part of	my ins	spection inc	luded se	veral ca	rs from th	e Zenith	Energy		
Seal Ap	plied	Hazard Class						ī	UN/NA ID												
Violation Recommended Yes V No									Latitude	):				Longitude:							
Written Notification to Railroad Action Code																					
	f Remedial A	Date(mm/					m/dd/yy	yyyy): Commen					ck?								
Item Initials/Milepost Equipment/Track # Type					Type/Kind		Defe	ect Sub	rule			Speed	Class	Train #/Site		SNFR	* RCL**	# of	Activity		
2	UTLX 683239		USC 173		0031 D1IV		IIV							N	N	Occ.***	Code TCT				
			173		,,						-	1			•	101					
Description  An inspection of UTLX 683239 found that the bottom outlet cap was loose and hanging from its chain.																					
Seal Applied Seal Removed Hazard Class UN/NA ID																					
Stat Kelliott										3					1267						
Violation Recommended Yes VNo								Latitude: Longitude:													
Written Notification to FRA of Remedial Action is:  Required Optional Railroad Action Code Date(mm/dd/yyyy):  Comments on back?												ck?									

OMB Approval No.: 2130-0509

## DEPARTMENT OF TRANSPORTATION

Inspector's ID No. Report No.

FEDERAL RAILROAD ADMINISTRATION (FRA)

Report Date

## INSPECTION REPORT

OMB Approval No.: 2130-0509

H4103		153 11/20		11/20/20	)/2018												
Item 3			Equipmer	nt/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule		Speed	Class	Train #/Site		SNFR*		# of Occ.***	Activity Code
	Description - [** Comment to Railroad/Company **] The defect was relayed to Nathan																
Seal Ap	oplied			Sea	l Removed				Hazard Class				UN/NA ID				
Violati	on Recommend	ed		Yes	<b>✓</b> No			Latitu	de:			L	ongitude:				
	Notification to of Remedial A		s:	Required	<b>✓</b> Optio	nal	ilroad Acti	on Code		Date(m	nm/dd/y	уууу):			Comm	ents on ba	ck?